

# Buildbotics Controller for Mega V XL

## V1.0 (work in progress)

This is a quick setup of the buildbotics controller for the Mega V XL

This controller will replace the black controller box that comes with the Mega V XL

You can also order the Mega V XL without the controller for \$400 less. (This is what I did)



<https://buildbotics.com/product/113/buildbotics-cnc-controller#image-0>

# Buildbotics Controller INFO

No external computer needed  
All control software included  
Motor drivers are built in  
No need for Mach 3 or LinuxCNC

## Features

4 stepper motor outputs (up to 6A each)  
Control and configure from your web browser  
Gamepad manual control  
Remote video monitoring (optional)  
Wired or wireless, WiFi network  
4 USB ports  
2 Switched load outputs  
8 Limit switch inputs  
PWM & RS485 (VFD) spindle control  
Z-axis probe interface  
250k steps/second on each motor output  
12 to 36 volt input  
Up to 1/256th microstepping  
S-Curve path planning  
Understands all common GCodes  
3D Visualization of GCode paths  
Accurate ETA and time estimates  
Free CAMotics GCode verification software  
100% Open-Source

## Included with purchase

The Buildbotics CNC Controller  
A Logitech F310 gamepad for manual control  
DB25 breakout box for easy access to all I/O  
4 x 10-foot motor cables  
1 x DC power supply cable  
2 x load switch cable stubs

I purchased the following Power Supply from Buildbotics  
Mean Well LRS-350-36 (36V, 350 watt power supply)

**Optional**

## **Mean Well LRS-350-36 36 Volt, 350 Watt Power Supply**



**Cable to connect to controller  
is included. Does not include an  
AC Power Cord**

# Connecting Motors to Buildbotics

You have two options for connecting the motors:

Option 1 – Cut aviation cables off motors and solder the wires to the supplied Buildbotics cables.

Option 2 – Buy aviation GX16 connectors and solder these to the supplied Buildbotics cables.

Now you can just plug the motor connectors into these connectors. (This is what I did)

Link to connectors

<https://tinyurl.com/2w27nw5b>




## How to Wire Stepper Motors

Connecting a stepper motor to a Buildbotics CNC Controller requires properly connecting the four wires from the driver to the right wires on the motor. Unfortunately, stepper motors come in a variety of configurations and it is not always immediately obvious how to hook them up. There are several characteristics that make stepper motors different from one another.

The Buildbotics CNC Controller provides four motor driver outputs through the back panel on ports labeled M0(X), M1(Y1), M2(Z), M3(Y2)

Each output has four pins. The upper left pin is B+, the lower left is B-, the upper right is A-, and the lower right is A+. B- and B+ must drive one of the motor coils and A- and A+ must drive the other motor coil.

Buildbotics provides pre-made cables that connect to the driver outputs on one end. These cables are color coded such that the A+ wire is red, the A- wire is black, the B+ wire is yellow, and the B- wire is purple.



Connecting 4-wire motors

Connecting 4-wire stepper motors requires connecting A+ and A- to one of the motor coils and B+ and B- to the other motor coil.

The trick is figuring out which wires make up the coil pairs. Here's two ways to figure this out:

Find the documentation for the motor. Assuming you don't already have it, read the model number off of the motor and then search for it on the Internet. With a little effort, it is usually possible to get a datasheet for the motor. The datasheet will usually specify the wires by A+, A-, B+, and B-, or at least show which wires by color attach to which coils.

If you can't find the datasheet, but have a multimeter, measure the resistance between any two of the motor wires. If you measure a near short, then that pair makes up one coil, and the other two wires make up the other coil. If it is an open, then measure between the first wire and another wire and then to the fourth wire until you find a near short. Notice that I say near short because the coil is a long thin wire and has some resistance. Once the pairs are identified, then arbitrarily assign one pair as "A" and the other as "B" and arbitrarily assign one wire as "+" and the other as "-" within each pair. Then connect the wires as shown. There is a 50% chance that the motor will turn backwards when connecting this way. If it does turn the wrong way simply click the reverse box in the motor settings or rewire the connector.

**INSERT PICTURES OF MY CONNECTORS WIRED  
UP HERE**

## Connecting the homing switches

I placed my homing switches in the following locations

X= default location - left side of the gantry as viewed from the front (X min)

Y= front left of the machine (Y min)

Z= default location – top of Z (Z max)


You then need to connect the wires to the DB25 breakout board pictured below.

Connect all of the black wires to a GND connection

Connect X to pin 3(motor 0 min)

Connect Y to pin 5 (motor 1 min)

Connect Z to pin 10 (motor 2 max)




# Configuring the Software



The screenshot shows the main interface of the Buildbotics CNC Controller. On the left is a vertical navigation menu with options: CONTROL, 3D VIEW, EDITOR, CAMERA, FILES, **SETTINGS** (highlighted with a red box and a red arrow), and DOCS. The main area displays the Buildbotics logo, version 'CNC Controller Demo v1.0.1', and a 'Camera Offline' status. A table shows the status of X, Y, and Z axes, all currently 'UNHOMED'. Below this is a 'Macros' section and a status table with fields for State, Velocity, Remaining, Message, Feed, ETA, Units, Speed, Line, Tool, Loads, and Progress.

Axis	Position	Absolute	Offset	State	⊗	🏠
X		0mm	0mm	UNHOMED	⚙️	⊗
Y		0mm	0mm	UNHOMED	⚙️	⊗
Z		0mm	0mm	UNHOMED	⚙️	⊗

State	READY	Velocity	0 m/min	Remaining	0:00
Message		Feed	0 mm/min	ETA	
Units	METRIC	Speed	0 (0) RPM	Line	0
Tool	0	Loads	1:Off 2:Off	Progress	0.00%



This screenshot shows the 'General Configuration' settings page. The 'Motors' dropdown menu is open, showing assignments for Motor 0, Motor 1, Motor 2, and Motor 3. Red arrows point from these motor names to the axis labels X, Y1, Z, and Y2 respectively. The 'units' dropdown is set to 'METRIC'. Below the configuration is a note about the 'units' setting and a 'GCode' section with a 'program-start' block containing G90, G17, and M0 commands.

**General Configuration**

units: METRIC

Note, `units` sets both the machine default units and the units used in motor configuration. GCode `program-start`, set below, may also change the default machine units.

**GCode**

```
program-start (Runs at program start)
G90 (Absolute distance mode)
G17 (Select XY plane)
M0 (MSG, Turn on Spindle)
```

# Motor 0 Configuration

## General

axis

## Power

enabled   
drive-current  amps  
idle-current  amps

Set this to 1000 to start then home your machine and then jog to the maximum limit and input that value here

## Motion

reverse   
microsteps  per full step (28.6k  $\mu$ step/sec)  
max-velocity  m/min (268 RPM)  
max-accel  km/min<sup>2</sup> (1.416 g)  
max-jerk  km/min<sup>3</sup> (7.08 g/min)  
step-angle  degrees (200 steps/rev)  
travel-per-rev  mm (279.5  $\mu$ m/step)

## Limits

min-soft-limit  mm  
max-soft-limit  mm  
min-switch  Pin 3   
max-switch  Pin 4

This will need to be calibrated. This is the value that worked for me.

## Homing

homing-mode   
search-velocity  m/min (9 RPM)  
latch-velocity  m/min  
latch-backoff  mm  
zero-backoff  mm

You may need to adjust this as well.

This sets the distance the machine backs off of the homing switch

This is the left side Y motor.

## Motor 1 Configuration

### General

axis

### Power

enabled

drive-current  amps

idle-current  amps

If the motors are turning the wrong way you can click this box to fix it

### Motion

reverse

microsteps  per full step (28.6k  $\mu$ step/sec)

max-velocity  m/min (268 RPM)

max-accel  km/min<sup>2</sup> (1.416 g)

max-jerk  km/min<sup>3</sup> (7.08 g/min)

step-angle  degrees (200 steps/rev)

travel-per-rev  mm (279.6  $\mu$ m/step)

### Limits

min-soft-limit  mm

max-soft-limit  mm

min-switch  Pin 5 

max-switch  Pin 8 

### Homing

homing-mode

search-velocity  m/min (9 RPM)

latch-velocity  m/min

latch-backoff  mm

zero-backoff  mm

# Motor 2 Configuration

## General

axis

## Power

enabled

drive-current  amps

idle-current  amps

## Motion

reverse

microsteps  per full step (65.8k  $\mu$ step/sec)

max-velocity  m/min (617 RPM)

max-accel  km/min<sup>2</sup> (0.708 g)

max-jerk  km/min<sup>3</sup> (7.08 g/min)

step-angle  degrees (200 steps/rev)

travel-per-rev  mm (40.5  $\mu$ m/step)

## Limits

min-soft-limit  mm

max-soft-limit  mm

min-switch  Pin 9 

max-switch  Pin 10 

## Homing

homing-mode

search-velocity  m/min (62 RPM)

latch-velocity  m/min

latch-backoff  mm

zero-backoff  mm

This is the right side Y motor

## Motor 3 Configuration

### General

axis  (slave motor)

### Power

drive-current  amps

idle-current  amps

### Motion

reverse